

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
NJ,
13-LOBRA,
2-

Ulysses S. Grant Cottage
(Howard Potter House)
995 Ocean Avenue
Long Branch
Monmouth County
New Jersey

HABS No. NJ-884

Jack E. Boucher, Photographer November, 1963

- NJ-884-1 WEST FRONT, FROM THE NORTHWEST
(5" x 7" print; 4" x 5" negative)
- NJ-884-2 WEST FRONT, FROM THE SOUTHWEST
- NJ-884-3 WEST FRONT AND SOUTH SIDE
- NJ-884-4 SOUTH SIDE AND EAST REAR
(5" x 7" print; 4" x 5" negative)
- NJ-884-5 EAST REAR
- NJ-884-6 NORTH SIDE AND WEST FRONT
(5" x 7" print; 4" x 5" negative)
- NJ-884-7 DETAIL, WEST FRONT, PORTE COCHERE
(5" x 7" print; 4" x 5" negative)
- NJ-884-8 DETAIL, WEST FRONT, THIRD STORY AND ROOF
(5" x 7" print; 4" x 5" negative)
- NJ-884-9 DETAIL, WEST FRONT, DORMER AND CORNICE
(5" x 7" print; 4" x 5" negative)
- NJ-884-10 DETAIL, SOUTH SIDE, SOLARIUM
(5" x 7" print; 4" x 5" negative)
- NJ-884-11 INTERIOR, FIRST FLOOR, MAIN STAIRCASE, FROM THE WEST
(5" x 7" print; 4" x 5" negative)
- NJ-884-12 INTERIOR, FIRST FLOOR, NORTH ROOM, DETAIL OF WINDOW
(5" x 7" print; 4" x 5" negative)
- NJ-884-13 DURING DEMOLITION, BULLDOZER PREPARING TO PULL AWAY PART OF PORCH
- NJ-884-14 DURING DEMOLITION, BULLDOZER PULLING AWAY SOLARIUM
- NJ-884-15 DURING DEMOLITION, BULLDOZER PUSHING OVER SOLARIUM
- NJ-884-16 DURING DEMOLITION, SHOWING THE DEBRIS OF THE SOLARIUM

- NJ-884-17 DURING DEMOLITION, THE PORCH ON THE WEST REAR BEGINNING TO COLLAPSE
- NJ-884-18 DURING DEMOLITION, SHOWING THE ROOF OF THE WEST REAR PORCH HITTING THE GROUND
- NJ-884-19 DURING DEMOLITION, SHOWING HOUSE SPLITTING IN HALF
(8" x 10" print; 4" x 5" negative)
- NJ-884-20 DURING DEMOLITION, SHOWING DEBRIS OF HOUSE
(5" x 7" print; 4" x 5" negative)
- NJ-884-21 Photocopy of drawing (from "The President's Cottage at Long Branch," Harper's Weekly, XIV, No. 711, 13 August 1870.)
Drawing taken from a photograph by E. W. Pacil
WEST FRONT AND SOUTH SIDE, SHOWING APPEARANCE OF HOUSE BEFORE ALTERATIONS AND ADDITIONS